



Kiln Striking

We recommend you make a sample bead and anneal at your regular temperature. Use the chart below to check its progress at each interval.

Kiln Temperature: _____

Color at 15 minutes: _____

Color at 30 minutes: _____

Color at 1 hour: _____

Color at 2 hours: _____

Color at 4 hours: _____

Please note, cycles of cooling and heating are what strikes a glass. To avoid the colors that appear in our flame struck paddle keep the glass hot until you're ready to anneal. Do not cool and reheat.

Always use proper ventilation.

Kiln striking silver glass by
Double Helix: Pandora

www.doublehelixglassworks.com

Pandora kiln struck at 1000°F



unstruck



15 minutes



30 minutes



1 hour




2 hours



4 hours



8 hours



flame struck +
5 hours